



The connection to the 4 to 20mA output of the PLC is as it is shown on the picture above, or if the output is 0 to 10V, as it is shown on the picture below. A external resistor 510 ohms is required.

